

VEHICLE INSPECTION REPORT

YP16AXM

Fiat Ducato Maxi 35 2.3 Multijet Tipper 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Location	Avonmouth	GVW	3500kg	CAP Clean	£4,400.00
Reg. date	01/04/2016	Colour	WHITE	CAP Average	£3,575.00
Year	2016	VIN	ZFA25000002A58683	CAP Below	£2,600.00
Mileage	98,844 Miles Not Warranted	Body Style	Tipper MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	6

WARNING LIGHT ON DASH, TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR






Spare

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Dented
Hail - Severe



3: Bonnet
Scratched
Over 25mm Thru Paint

4: Front TowEye Cvr
Missing
Replace



5: Bumper Front Grill
Broken
Replace

6: Bumper Front
Insecure
Action Required



7: Moulding of Wing
Broken
Replace

8: Wing not
Dented
Hail - Severe



9: Wing nsf
Scratched
Over 25mm Thru Paint

10: Door Moulding nsf
Missing
Replace



11: Door nsf
Scratched
Over 25mm Thru Paint

12: Wing Front Arch Extension ns
Broken
Replace



13: Sill ns
Dented
With Paint Damage

14: B Post ns
Dented
With Paint Damage



15: Qtr Panel nsr
Dented
With Paint Damage

16: Panel Rear
Dented
With Paint Damage



17: B Post os
Scratched
Over 25mm Thru Paint

18: Qtr Panel osr
Dented
With Paint Damage



19: Door osf
Scratched
Over 25mm Thru Paint

20: Door osf
Dented
With Paint Damage



21: Door Moulding osf
Broken
Replace

22: Door Mirror Assy osf
Broken
Replace



23: Bumper Front
Insecure
Action Required

24: General Interior
Soiled
Light



25: Seat Base Cover osf
Holed
Over 3mm

26: Carpets Front
Broken
Replace



27: Fascia Trim
Damaged
Replace

28: Fascia Trim
Damaged
Replace



29: Fascia Trim
Damaged
Replace

30: Seat Base Cover nsf
Holed
Over 3mm



31: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	Fault
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		