

VEHICLE INSPECTION REPORT

WS19ACY

Fiat Ducato 35 2.3 Multijet II 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£4,575.00
Reg. date	06/08/2019	Colour	WHITE	CAP Average	£3,950.00
Year	2019	VIN	ZFA25000002L48498	CAP Below	£3,075.00
Mileage	105,086 Miles Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	30/06/2027	Gears	6

OUTSTANDING RECALL SIDE LOAD DOOR, TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage

4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Chipped
Multiple Chips



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Qtr Panel nsr
Chipped
Multiple Chips



11: Door osr
Chipped
Over 5mm

12: C Post os
Dented
With Paint Damage



13: C Post os
Dented
With Paint Damage

14: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



15: Wing osf
Dented
With Paint Damage

16: Door Pad osf
Soiled
Heavy



17: Carpets Front
Holed
Over 3mm

18: Seat Base Cover osf
Holed
Over 3mm



19: Seat Base Cover nsf
Soiled
Heavy

20: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		