

# VEHICLE INSPECTION REPORT

**WX20KME**

## Fiat Ducato 35 2.3 Multijet I 140PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

|           |                           |            |                   |             |           |
|-----------|---------------------------|------------|-------------------|-------------|-----------|
| Location  | Doncaster                 | GVW        | 3500kg            | CAP Clean   | £6,275.00 |
| Reg. date | 29/06/2020                | Colour     | WHITE             | CAP Average | £5,500.00 |
| Year      | 2020                      | VIN        | ZFA25000002N83621 | CAP Below   | £4,375.00 |
| Mileage   | 91,345 Miles<br>Warranted | Body Style | Panel Van         | Gearbox     | MANUAL    |
| Fuel Type | DIESEL                    | MOT Due    | 15/07/2027        | Gears       | 6         |

\*WARNING LIGHTS ON DASH\* SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, AD-BLUE

### Tyres

NSF

NSR

OSF


OSR





Spare

## Features

- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


## Photos








## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Thru Paint

2: Bumper Front  
Scratched  
25 to 100mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips

4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm

6: Door Moulding nsf  
Missing  
Replace



7: Qtr Panel nsr  
Dented  
Over 30mm

8: Qtr Panel osr  
Dented  
Over 30mm





9: Door osf  
Scratched  
Over 25mm Thru Paint

10: Door Pad osf  
Soiled  
Heavy



11: Carpets Front  
Holed  
Over 3mm

12: Seat Base Cover osf  
Torn  
Over 3mm



13: Seat Base Cover nsf  
Soiled  
Heavy

14: Dash Warning Lights  
Displayed  
No Action

## Interior

|                         |      |                             |       |
|-------------------------|------|-----------------------------|-------|
| <b>Carpet Condition</b> | Poor | <b>Upholstery Condition</b> | Poor  |
| <b>Seat Condition</b>   | Poor | <b>Odour</b>                | No    |
| Engine Runs             | OK   | No Excessive Smoking        | OK    |
| EML light illuminated   | OK   | DPF light illuminated       | Fault |
| ABS light illuminated   | OK   |                             |       |