

VEHICLE INSPECTION REPORT

KU68BAV

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Colour WHITE

Axle Combi 4x2

Reg. date 17/09/2018

VIN XLRAEL3700L478562

Rear Suspension Steel

Year 2018

Body Style Curtainside

Rear Doors Barn

Mileage 274,939 Km Warranted

MOT Due 30/09/2026

Tail Lift Tuckaway

Fuel Type DIESEL

Cab Type SLEEPER CAB

GVW 18000kg

Gearbox AUTOMATIC

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint

2: Screen Front
Chipped
UpTo 10mm



3: Bonnet
Cracked
Replace

4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Bumper Front
Scratched
25 to 100mm Thru Paint

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

8: Wing Front Arch Extension ns
Broken
Replace



9: Door Mirror Glass ns
Broken
Replace

10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

12: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



13: Door osf
Scratched
Over 25mm Not Thru Paint

14: Door osf
Chipped
Edge Chip

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	