

VEHICLE INSPECTION REPORT

KR68PZN

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Colour WHITE

Axle Combi 4x2

Reg. date 25/01/2019

VIN XLRAEL3700L483120

Rear Suspension Steel

Year 2019

Body Style Curtainside

Rear Doors Barn

Mileage 314,784 Km Warranted

MOT Due 31/03/2027

Tail Lift Tuckaway

Fuel Type DIESEL

Cab Type DAY CAB

GVW 18000kg

Gearbox AUTOMATIC

SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4





OSO1 OSO2 OSO3 OSO4

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Poor Previous Repair
Poor Colour



5: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



6: Wing Front Arch Extension ns
Broken
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Qtr Panel nsr
Hole
Over 10mm





9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

10: Door osf
Chipped
Edge Chip



11: Seat Base Cover osf
Holed
Over 3mm

12: Seat Back Cover osf
Missing
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		