

VEHICLE INSPECTION REPORT

WK18JPU

Volvo FH 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Avonmouth

Reg. date 01/03/2018

Year 2018

Mileage 596,835 Km Not Warranted

Fuel Type Diesel

GVW 44000kg

Colour BLACK

VIN YV2RTY0C9JB855234

Body Style Tractor Unit

MOT Due Expired

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

WARNING LIGHTS ON DASH BATTERY ISSUES*, REAR-LIFT, SLIDING 5TH WHEEL

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4



Features

- Bluetooth connection
- Front electric windows
- Partial leather seat trim
- Radio/CD
- Drivers airbag
- Electric sunroof
- Central locking
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Number Plate Front
Missing
Replace

4: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Cracked
Replace

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




9: Door Mirror Glass ns
Broken
Replace

10: Qtr Panel Trim ns
Missing
Replace



11: Qtr Panel osr
Chipped
Multiple Chips

12: Door osf
Chipped
Multiple Chips



13: Door osf
Dented
Over 30mm

14: Fascia Trim
Damaged
Replace



15: Seat Base Cover osf
Holed
Over 3mm

16: Dash Warning Lights
Displayed
No Action



17: Fascia Trim
Missing
Replace

18: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		