

VEHICLE INSPECTION REPORT

WV70FXF

Vauxhall Movano 3500 2.3 Turbo D 135ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Avonmouth

Reg. date 08/09/2020

Year 2020

Mileage 85,571 Miles Not Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN W0VMR8600LB212876

Body Style Panel Van L2

MOT Due 07/09/2026

CAP Clean £6,575.00

CAP Average £5,775.00

CAP Below £4,625.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR



Spare

Features


- Bluetooth connection
- USB/iPod interface
- Central locking
- Rear parking sensor
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos






Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Wing nsf
Chipped
Multiple Chips

4: Door nsf
Chipped
1 To 5



5: B Post ns
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

8: Sill ns
Dented
Over 30mm



9: Panel Rear
Scratched
Over 25mm Thru Paint

10: Door osr
Dented
With Paint Damage



11: Lamp osr
Broken
Replace

12: Qtr Panel osr
Poor Previous Repair
Poor Paint



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

14: Sill os
Scratched
Over 25mm Thru Paint



15: Dash Warning Lights
Displayed
No Action

16: Fascia Panel
Broken
Replace



17: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	Fault