

# VEHICLE INSPECTION REPORT

**BU69TNL**

## Daf LF 230

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

|           |                      |            |                   |                 |          |
|-----------|----------------------|------------|-------------------|-----------------|----------|
| Location  | Bedford              | Colour     | WHITE             | Axle Combi      | 4x2      |
| Reg. date | 15/11/2019           | VIN        | XLRAEL3700L490739 | Rear Suspension | Air      |
| Year      | 2019                 | Body Style | Fridge Box        | Rear Doors      | Roller   |
| Mileage   | 425,440 Km Warranted | MOT Due    | 30/09/2026        | Tail Lift       | Tuckaway |
| Fuel Type | DIESEL               | Cab Type   | DAY CAB           |                 |          |
| GVW       | 18000kg              | Gearbox    | MANUAL            |                 |          |

\*WARNING LIGHT ON DASH\* THERMOKING T-1000R UNIT, STANDY PLUG, SINGLE SIDE BARN DOOR


### Tyres




|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
UpTo 25mm Not Thru Paint



2: Screen Front  
Chipped  
UpTo 10mm



3: Bonnet  
Chipped  
Multiple Chips

4: Bumper Front  
Scratched  
25 to 100mm Thru Paint



5: Bumper Front  
Scratched  
25 to 100mm Thru Paint

6: Door Mirror Assy nsf  
Broken  
Replace



7: Wing nsf  
Scratched  
Over 25mm Thru Paint

8: Door nsf  
Chipped  
1 To 5



9: Wing Front Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

12: Door osf  
Chipped  
Edge Chip



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

14: Wing Front Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



15: Door osf  
 Scratched  
 Over 25mm Not Thru Paint

16: Seat Base Cover osf  
 Holed  
 Over 3mm

Interior

| Carpet Condition         |       | Average | Upholstery Condition                           |    | Average |
|--------------------------|-------|---------|------------------------------------------------|----|---------|
| Seat Condition           |       | Average | Odour                                          |    | -       |
| Engine Runs              | OK    |         | Gearbox 1st and Reverse Test                   | OK |         |
| Brakes                   | OK    |         | Clutch Slip Test from Static                   | OK |         |
| Parking Brake            | OK    |         | Gearbox Static Gear Selection (engine running) | OK |         |
|                          |       |         | No Excessive Smoking                           | OK |         |
| EML light illuminated    | Fault |         | Oil warning light illuminated                  | OK |         |
| Airbag light illuminated | OK    |         | DPF light illuminated                          | OK |         |
| ABS light illuminated    | OK    |         | Service indicator light illuminated            | OK |         |