

VEHICLE INSPECTION REPORT

KX16ZWM

Scania P 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Bedford

GVW 32000kg

Gearbox AUTOMATIC

Reg. date 11/05/2016

Colour RED

Axle Combi 8x4

Year 2016

VIN YS2P8X40005414650

Rear Suspension Steel

Mileage 325,655 Km Warranted

Body Style Refuse Collector

Fuel Type DIESEL

Cab Type DAY CAB

NO REVERSE GEAR, PARTS REMOVED FROM STEERING WHEEL, WINDSCREEN CRACKED SINGLE LIFT


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing of
Cracked
Replace

2: Screen Front
Cracked
Replace



3: Bonnet
Cracked
Replace



4: Bumper Front
Dented
Between 10mm + 30mm



5: Panel Front
Cracked
Replace



6: Headlamp ns
Broken
Replace



7: Bumper Front
Scratched
25 to 100mm Thru Paint

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm




9: Door Mirror Assy nsf
Broken
Replace

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Wing Front Arch Extension os
Broken
Replace



13: Centre Console Front
Missing
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	