

VEHICLE INSPECTION REPORT

LN68ZKO

Daf LF 180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details


Location	Bedford	GVW	7500kg	Cab Type	DAY CAB
Reg. date	05/10/2018	Colour	WHITE	Gearbox	MANUAL
Year	2018	VIN	XLRAEL1500L475732	Axle Combi	4x2
Mileage	101,200 Km Not Warranted	Body Style	Sweeper	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	30/11/2026		



SCARAB BODY, 3470 SWEEPING HOURS, 6773 RUNNING HOURS

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel Arch Extension ns
Broken
Replace

6: Bumper Rear
Rusted
Over 5mm



7: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK