

# **VEHICLE INSPECTION REPORT**



## Peugeot Expert 1000 1.5 BLUEHDi 100PS PROFESSIONAL

| Inspection      |                  | Vehicle    |                   |           |            |
|-----------------|------------------|------------|-------------------|-----------|------------|
| Serious Damage? | No               | VAT        | Plus VAT          |           |            |
|                 |                  | V5         | Present           |           |            |
| Details         |                  |            |                   |           |            |
| Reg. date       | 28/04/2023       | VIN        | VF3VBYHRMP7801384 | CAP Below | £11,050.00 |
| Year            | 2023             | Body Style | Panel Van LWB     | Gearbox   | MANUAL     |
| Mileage         | 21,483 Miles Not | MOT Due    | 27/04/2026        | Gears     | 6          |

| mileage   | 21,403 Miles NOL | MOT Due     | 27/04/2026 | Gears | o |  |
|-----------|------------------|-------------|------------|-------|---|--|
|           | Warranted        | CAP Clean   | £13,300.00 |       |   |  |
| Fuel Type | Diesel           | CAP Average | £12,550.00 |       |   |  |
| Colour    | BLACK            |             | ,          |       |   |  |

#### AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

| Tyres        |  |  |  |
|--------------|--|--|--|
| Tyres<br>NSF |  |  |  |
| NSR          |  |  |  |
| OSF          |  |  |  |
| OSR          |  |  |  |
| OSR<br>Spare |  |  |  |

### **Features**

- Bluetooth connection
- Auxiliary input socket
- Drivers airbag
- Cruise control
- Digital radio Passenger airbag
- Park assist camera Air conditioning .
- Central locking
- Rear parking sensor Front electric windows
- Cloth seat trim

### **Photos**



**Commercial Vehicle Auctions Limited** 


































## **Condition Check**



## Damage Photos



1: Bumper Front Scratched Over 100mm Thru Paint



2: Panel Front Scratched Over 25mm Thru Paint





3: Bonnet Chipped Multiple Chips



5: Door osr Scratched Over 25mm Thru Paint



6: Qtr Panel osr Scratched Over 25mm Not Thru Paint

4: Door nsr

Scratched

Over 25mm Thru Paint



7: Qtr Panel osr Scratched Over 25mm Not Thru Paint



8: Qtr Panel osr Scratched Over 25mm Thru Paint





9: Door osf Scratched Over 25mm Thru Paint 10: Door osf Dented With Paint Damage

#### Interior

| Carpet Condition<br>Seat Condition | OK<br>OK |    | Upholstery Condition<br>Odour | OK<br>No |    |
|------------------------------------|----------|----|-------------------------------|----------|----|
| Engine Runs                        |          | OK | No Excessive Smoking          |          | ОК |
| EML light illuminated              |          | OK | DPF light illuminated         |          | OK |
| ABS light illuminated              |          | OK |                               |          |    |