

VEHICLE INSPECTION REPORT

RO23LVL

Peugeot Expert 1000 1.5 BLUEHDi 100PS PROFESSIONAL

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
Details					
Reg. date	28/04/2023	VIN	VF3VBYHRMP7801382	CAP Below	£10,100.00
Year	2023	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	36,883 Miles Not Warranted	MOT Due	27/04/2026	Gears	6
		CAP Clean	£12,150.00	-	
Fuel Type	Diesel	CAP Average	£11,450.00		
Colour	BLACK		•		

AD-BLUE, TWIN SIDE LOAD DOOR, E/MIRRORS

The block, Titlit olde book, Er will troke	
Tyres	
Tyres NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- · Park assist camera
- Front electric windows
- Cloth seat trim
- · Auxiliary input socket
- Drivers airbag

Photos























Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint



3: Qtr Panel nsr Scratched Over 25mm Thru Paint



4: Qtr Panel nsr Scratched Over 25mm Thru Paint



5: Qtr Panel nsr Scratched Over 25mm Thru Paint



6: Door nsr Scratched Over 25mm Thru Paint



7: Door osr Dented Between 10mm + 30mm



8: Door osr Scratched Over 25mm Thru Paint



9: Door osr Scratched Over 25mm Thru Paint



10: Door osr Scratched UpTo 25mm Thru Paint



11: Qtr Panel osr Scratched Over 25mm Thru Paint



12: Qtr Panel osr Scratched Over 25mm Thru Paint



13: Door osf Chipped Multiple Chips



14: Qtr Panel osr Scratched Over 25mm Thru Paint



15: Screen Front Chipped Over 10mm



16: Seat Base Cover osf Soiled Heavy



17: Seat Base Cover nsf Soiled Heavy

Interior

Carpet Condition	OK	Up	holstery Condition	OK	
Seat Condition	Poor	Oc	lour	-	
Engine Runs		OK N	No Excessive Smoking		OK
EML light illuminated		OK [C DPF light illuminated		OK
ABS light illuminated		OK			