

VEHICLE INSPECTION REPORT

C467466

FRUEHAUF TIPPER TASSC

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 N/A

Details


Location	Avonmouth	Fuel Type		MOT Due	28/02/2027
Reg. date	01/01/2017	Colour	ORANGE	Brakes	Disc
Year	2017	VIN	SFRWADDA3HG149201	Axle Combi	Tri
Mileage	Not Showing	Body Style	Trailer	Rear Suspension	Air











JOST AXLES, ALUMINIUM BODY, SHEETING SYSTEM, WEIGH SYSTEM, RAISE & LOWER VALVE, AUTO TAILGATE, QUICKSILVER BEDLINER, 70 CUBIC YARD, TASSC REG, (LAST 3 LOADS)

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
Multiple Chips

6: Door osf
Chipped
Multiple Chips



7: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint

8: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



9: Bumper Front
Scratched
25 to 100mm Thru Paint

10: Switches And Controls
Missing
Replace



11: Dash Warning Lights
Displayed
No Action

12: Seat Base Cover osf
Burn
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			