

# VEHICLE INSPECTION REPORT

**NX21UPA**

## Man TGX 18.640

**Non Runner**  
Inspection

|                        |    |                |                |
|------------------------|----|----------------|----------------|
| <b>Serious Damage?</b> | No | <b>Vehicle</b> |                |
|                        |    | <b>VAT</b>     | Plus VAT       |
|                        |    | <b>V5</b>      | Buyer To Apply |

### Details

|                  |                          |                   |                   |                        |           |
|------------------|--------------------------|-------------------|-------------------|------------------------|-----------|
| <b>Location</b>  | Doncaster                | <b>GVW</b>        | 34000kg           | <b>Gearbox</b>         | AUTOMATIC |
| <b>Reg. date</b> | 10/03/2021               | <b>Colour</b>     | BLUE              | <b>Axle Combi</b>      | 4x2       |
| <b>Year</b>      | 2021                     | <b>VIN</b>        | WMA06KZZXMM881884 | <b>Rear Suspension</b> | Air       |
| <b>Mileage</b>   | 551,843 Km Not Warranted | <b>Body Style</b> | Tractor Unit      |                        |           |
| <b>Fuel Type</b> | Diesel                   | <b>Cab Type</b>   | GX CAB            |                        |           |

\*FRONT WHEELS LOOSE, WARNING LIGHTS ON DASH\*

### Tyres

|              |             |             |             |             |
|--------------|-------------|-------------|-------------|-------------|
| <b>NSF</b>   | <b>NSI1</b> | <b>NSI2</b> | <b>NSI3</b> | <b>NSI4</b> |
| <b>OSF</b>   | <b>OSI1</b> | <b>OSI2</b> | <b>OSI3</b> | <b>OSI4</b> |
| <b>Spare</b> | <b>NSO1</b> | <b>NSO2</b> | <b>NSO3</b> | <b>NSO4</b> |
|              | <b>OSO1</b> | <b>OSO2</b> | <b>OSO3</b> | <b>OSO4</b> |



## Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Metallic Paint
- Central locking
- Leather seat trim

## Photos












## Condition Check



## Damage Photos




1: Screen Front  
Cracked  
Replace

2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front Moulding  
Scratched (Painted)  
Over 25mm Thru Paint

4: Bumper Front Moulding  
Broken  
Replace



5: Door Moulding of  
Scratched (Painted)  
Over 25mm Thru Paint

6: Dash Warning Lights  
Displayed  
No Action

Interior

|                         |       |                                     |       |
|-------------------------|-------|-------------------------------------|-------|
| <b>Carpet Condition</b> | OK    | <b>Upholstery Condition</b>         | OK    |
| <b>Seat Condition</b>   | OK    | <b>Odour</b>                        | -     |
| Engine Runs             | OK    | No Excessive Smoking                | OK    |
| EML light illuminated   | Fault | DPF light illuminated               | OK    |
| ABS light illuminated   | Fault | Service indicator light illuminated | Fault |