

VEHICLE INSPECTION REPORT

WS19AEJ

Fiat Ducato 35 II 2.3 Multijet 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	31282
		Cap Code	FIDU2335M3HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£3,450.00
Reg. date	06/08/2019	Colour	WHITE	CAP Average	£2,975.00
Year	2019	VIN	ZFA25000002L55970	CAP Below	£2,350.00
Mileage	150,836 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	23/06/2027	Gears	6

WARNING LIGHTS ON DASH SIDE LOAD DOOR, TOW BAR, E/MIRRORS, RACKING, DEADLOCKS (NO KEYS)

Tyres





NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Chipped
Multiple Chips



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Fascia Panel
Missing
Replace



8: Carpets Front
Holed
Over 3mm



9: Seat Base Cover osf
Holed
Over 3mm



10: Seat Base Cover nsf
Soiled
Heavy



11: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		Fault	DPF light illuminated		OK
ABS light illuminated		OK			