

VEHICLE INSPECTION REPORT

BN19VEM

Fiat Ducato Maxi 2.3 MULTIJET 150PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 12/03/2019

Year 2019

Mileage 24,162 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002H01371

Body Style Panel Van LWB

MOT Due Expired

CAP Clean £7,550.00

CAP Average £6,600.00

CAP Below £5,275.00

Gearbox MANUAL

Gears 6

AD BLUE, SINGLE SIDE DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Grille Front
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: General Exterior
Soiled
Light



7: General Exterior
Soiled
Light



8: General Exterior
Soiled
Light



9: General Exterior
Soiled
Light



10: B Posts
Dented
Between 10mm + 30mm



11: General Exterior
Soiled
Light



12: General Exterior
Soiled
Light



13: General Exterior
Soiled
Light



14: General Exterior
Soiled
Light



15: General Exterior
Soiled
Light



16: General Exterior
Soiled
Light



17: General Exterior
Soiled
Light



18: Door Mirror Assy osf
Broken
Replace



19: Other
N/A
N/A



20: Other
N/A
N/A



21: Other
N/A
N/A



22: Carpets Front
Holed
Over 3mm



23: Other
N/A
N/A



24: Other
N/A
N/A



25: Other
N/A
N/A



26: Other
N/A
N/A



27: Other
N/A
N/A

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		Average	
Average		No	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK