

VEHICLE INSPECTION REPORT

DK17LNG

Man TGL 12.220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Bedford	GVW	12000kg	Cab Type	DAY CAB
Reg. date	06/06/2017	Colour	BLUE	Gearbox	MANUAL
Year	2017	VIN	WMAN05ZZ6HY360782	Axle Combi	4x2
Mileage	411,180 Km Warranted	Body Style	Curtainside	Rear Suspension	Steel
Fuel Type	DIESEL	MOT Due	28/02/2027	Rear Doors	Barn

SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST AVAILABLE

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Screen Front
Chipped
Over 10mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Door nsf
Scratched
UpTo 25mm Not Thru Paint



9: Bumper Rear
Rusted
Over 5mm

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip

12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

14: Seat Base Cover osf
Holed
Over 3mm



15: Door Pad osf
Broken
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK