

VEHICLE INSPECTION REPORT

ND75MVM

Mercedes-Benz Sprinter 315 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Location	Doncaster	GVW	3500kg	MOT Due	25/11/2028
Reg. date	26/11/2025	Colour	WHITE	Gearbox	MANUAL
Year	2025	VIN	W1V3H3FZ5TN370101	Gears	6
Mileage	27,521 Miles Warranted	Body Style	Luton	Tail Lift	Column
Fuel Type	DIESEL	Service history	None		

WARNING LIGHT ON DASH AD-BLUE, E/MIRRORS

Tyres

NSF

NSR

OSF



OSR





Spare

Features


- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos





Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Seat Base Cover osf
Soiled
Heavy

4: Seat Base Cover nsf
Soiled
Heavy



5: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
Airbag light illuminated		Fault			
ABS light illuminated		OK			