

VEHICLE INSPECTION REPORT

NL25VRV

Mercedes-Benz Sprinter 313 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	Colour	WHITE	CAP Average	£21,200.00
Reg. date	12/05/2025	VIN	W1V3HCFZ8SP739536	CAP Below	£19,050.00
Year	2025	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	71,424 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	11/05/2028		
GVW	3500kg	CAP Clean	£22,050.00		

WARNING LIGHT ON DASH SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF



OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel nsr
Dented
Over 30% Of Panel

4: Qtr Panel nsr
Dented
Over 30% Of Panel




5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Door nsr
Dented
With Paint Damage

8: Door nsr
Dented
With Paint Damage



9: Badgedecal Rear
Missing
Replace

10: Door osr
Dented
With Paint Damage



11: Bumper Rear Moulding
Broken
Replace

12: Lamp osr
Broken
Replace



13: Qtr Panel osr
Dented
With Paint Damage

14: Qtr Panel osr
Dented
With Paint Damage



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
With Paint Damage

18: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



19: Seat Base Cover osf
Soiled
Heavy

20: Seat Base Cover nsf
Soiled
Heavy



21: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK		
ABS light illuminated	OK		