

VEHICLE INSPECTION REPORT

BT68LXE

Iveco Daily 35-140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 07/01/2019

Year 2019

Mileage 68,581 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZCFC1358105258078

Body Style Panel Van LWB

Service history None

MOT Due 02/06/2027

CAP Clean £5,000.00

CAP Average £4,300.00

CAP Below £3,375.00

Gearbox MANUAL

Gears 6

RACKING IN REAR, E/MIRRORS, AD-BLUE, HEATED WINDSCREEN, WB 4100

Tyres

NSF

NSR

OSF


OSR




Spare

Features

- Bluetooth connection
- Radio/CD
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Wing osf
Dented
Over 30mm

2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Cracked
Replace

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage

8: Door nsr
Dented
Over 30mm



9: Door osr
Dented
Over 30mm

10: Qtr Panel osr
Dented
Over 30mm



11: Door osf
Dented
Over 30mm

12: Carpets Front
Holed
Over 3mm



13: Seat Base Cover osf
Holed
Over 3mm

14: Fascia Trim
Damaged
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		