

VEHICLE INSPECTION REPORT

CN72WLF

Mercedes-Benz Vito 114 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Avonmouth	GVW	3050kg	CAP Clean	£15,500.00
Reg. date	31/10/2022	Colour	BLACK	CAP Average	£13,850.00
Year	2022	VIN	W1V44760324163918	CAP Below	£11,350.00
Mileage	33,356 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	30/10/2026	Gears	6

AD BLUE, TWIN SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Front electric windows
- Cloth seat trim
- Cruise control
- Digital radio
- Drivers airbag
- Park assist camera
- USB/iPod interface
- Passenger airbag
- Rear parking sensor
- Air conditioning
- Central locking

Condition Check




Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint



2: Door nsf
Scratched
UpTo 25mm Not Thru Paint



3: Door nsf
Chipped
Edge Chip

4: Fuel Flap
Scratched
UpTo 25mm Not Thru Paint



5: Door osr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



7: Bumper Reflector osr
Broken
Replace

8: Bumper Rear
Scratched
Over 25mm Not Thru Paint



9: Door osr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel Trim os
Scuffed
Over 25mm



11: Door osr
Scratched
Over 25mm Not Thru Paint

12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		
		Radio	OK