

VEHICLE INSPECTION REPORT

OE21KYC

Mercedes-Benz Sprinter 315cdi L3 Diesel Rwd 3.5t Progressive Dropside

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Location	Avonmouth	Colour	WHITE	CAP Below	£7,100.00
Reg. date	19/08/2021	VIN	W1V9071352N159632	Gearbox	MANUAL
Year	2021	Body Style	Dropside L3	Gears	6
Mileage	118,950 Miles Warranted	MOT Due	21/08/2027	Tail Lift	Column
Fuel Type	DIESEL	CAP Clean	£9,675.00		
GVW	3500kg	CAP Average	£8,650.00		

ENTERTAINMENT SYSTEM INOP, TOW BAR



Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Central locking
- Park assist camera
- Cloth seat trim
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Front TowEye Cvr
Missing
Replace




3: Bumper Front Moulding
Broken
Replace

4: Bonnet
Scratched
Over 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint

8: B Post ns
Scratched
Over 25mm Thru Paint



9: B Post os
Chipped
Multiple Chips

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Multiple Chips

12: Wing osf
Scratched
Over 25mm Thru Paint



13: Bumper Front
Scratched
Over 100mm Thru Paint

14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Seat Base Cover osf
 Holed
 UpTo 3mm

16: Fascia Trim
 Damaged
 Replace



17: In Car Entertainment
 Broken
 Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			