

VEHICLE INSPECTION REPORT

CP17KPJ

Iveco Daily 50-150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Avonmouth

Reg. date 26/06/2017

Year 2017

Mileage 99,042 Km Warranted

Fuel Type Diesel

GVW 5200kg

Colour WHITE

VIN ZCFC150B305138491

Body Style Access Platform

MOT Due 31/03/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

VERSALIFT ETM38-F PLATFORM (YEAR 2016), V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Radio/CD
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Front TowEye Cvr
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Dented
Hail - Severe



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Chipped
Multiple Chips



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



10: Qtr Panel nsr
 Scratched
 Over 25mm Not Thru Paint



11: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint



12: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint



13: Qtr Panel nsr
 Rusted
 Over 5mm



14: Qtr Panel osr
 Dented
 With Paint Damage



15: Qtr Panel osr
Chipped
Multiple Chips



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



18: Door osf
Chipped
Multiple Chips



19: Door Mirror Assy osf
Broken
Replace



20: Wing osf
Chipped
1 To 5



21: Bumper Front
Scratched
Over 100mm Thru Paint



22: Centre Console Front
Holed
Over 3mm



23: Fascia Trim
Damaged
Replace



24: Fascia Trim
Missing
Replace



25: Fascia Panel
Missing
Replace



26: Centre Console Front
Scuffed
Over 25mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		