

VEHICLE INSPECTION REPORT

CU15CYX

Ford Transit 350 2.2 TDCi 100ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£2,500.00
Reg. date	09/03/2015	Colour	WHITE	CAP Average	£2,025.00
Year	2015	VIN	WF0XXXTTGXEM45546	CAP Below	£1,425.00
Mileage	154,472 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	27/11/2026	Gears	6

SIDE LOAD DOOR, RACKING, DEADLOCKS, INVERTER, LADDER STOW, TOW BAR, ROOF RACK, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF


OSR





Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Dented
With Paint Damage




5: Door nsf
Chipped
Multiple Chips

6: Door nsf
Dented
With Paint Damage




7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Chipped
Multiple Chips

10: Qtr Panel nsr
Chipped
Multiple Chips



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osr
Chipped
Multiple Chips

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint




15: Qtr Panel osr
Scratched
Over 25mm Thru Paint

16: Qtr Panel osr
Chipped
Multiple Chips



17: Qtr Panel osr
Dented
With Paint Damage

18: Qtr Panel osr
Dented
With Paint Damage



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint

20: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



21: Door osf
Chipped
Multiple Chips

22: Door Mirror Assy osf
Broken
Replace



23: Door Pad osf
Soiled
Heavy

24: Seat Base Cover osf
Holed
Over 3mm



25: Seat Back Cover osf
Soiled
Heavy

26: Seat Base Cover nsf
Soiled
Heavy



27: Seat Back Cover nsf
Soiled
Heavy

28: Steering Wheel
Damaged
Replace



29: Fascia Panel
Scuffed
Over 25mm

30: Fascia Panel
Scuffed
Over 25mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		