

VEHICLE INSPECTION REPORT

KX67AKK

Isuzu D-Max 2.5

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	Colour	WHITE	CAP Below	£3,975.00
Reg. date	20/09/2017	VIN	MPATFS87JHT006369	Gearbox	MANUAL
Year	2017	Body Style	Access Platform	Gears	6
Mileage	80,183 Miles Warranted	MOT Due	19/09/2026	Axle Combi	4x4
Fuel Type	Diesel	CAP Clean	£6,425.00		
GVW	3500kg	CAP Average	£5,350.00		

COLLECTED WITH MAJOR BOOM ISSUES V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES, PALFINGER P130A PLATFORM (YEAR 2017)

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Park assist camera
- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm

2: Bonnet
Scratched
Over 25mm Thru Paint



3: Roof
Rusted
Over 5mm

4: Wing nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Door nsf
Dented
With Paint Damage



7: Door osf
Chipped
Edge Chip

8: B Post os
Dented
With Paint Damage



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

10: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	