

VEHICLE INSPECTION REPORT

FL69XGJ

Vauxhall Vivaro 2900 1.5d 100PS Edition

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	44124
		Cap Code	VAVI15191DVIDTM2 3 L

Details

Location	Doncaster	GVW	2830kg	CAP Clean	£6,600.00
Reg. date	31/12/2019	Colour	WHITE	CAP Average	£5,675.00
Year	2019	VIN	VXEVBVYHRKL7006858	CAP Below	£4,425.00
Mileage	62,804 Miles Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	28/06/2027	Gears	6


WARNING LIGHT ON DASH TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE





Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Dented
With Paint Damage



8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Dash Warning Lights
Displayed
No Action



12: Air Vents osf
Missing
Replace



13: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	OK	Odour	Poor
Engine Runs	OK	No Excessive Smoking	No
EML light illuminated	OK	Oil warning light illuminated	Fault
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	Fault