

VEHICLE INSPECTION REPORT

BD68YGX

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Doncaster

Reg. date 08/01/2019

Year 2019

Mileage 61,849 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN ZCFC1358105261658

Body Style Panel Van LWB

Service history None

MOT Due 02/06/2027

CAP Clean £5,200.00

CAP Average £4,475.00

CAP Below £3,500.00

Gearbox MANUAL

Gears 6

WB 3520

Tyres

NSF

NSR

OSF

OSR






Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Cracked
Replace



3: Wing nsf
 Scratched
 Over 25mm Thru Paint

4: Door Mirror Assy nsf
 Scuffed (Unpainted)
 Over 100mm



5: Door nsf
 Scratched
 Over 25mm Thru Paint

6: Qtr Panel nsr
 Dented
 Over 30mm



7: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint

8: Door nsr
 Dented
 With Paint Damage




9: Door nsr
Dented
Over 30mm



10: Door osr
Dented
Over 30mm



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover osf
Torn
Over 3mm

16: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		OK	
Poor		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		