

VEHICLE INSPECTION REPORT

G18TPT

Mercedes-Benz Actros 2630

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details

Location	Avonmouth	Colour	WHITE	Axle Combi	6x2
Reg. date	28/05/2014	VIN	WDB9630202L860187	Rear Suspension	Air
Year	2014	Body Style	Curtainside	Rear Doors	Barn
Mileage	611,558 Km Incorrect	Cab Type	CLASSICSPACE CAB		
Fuel Type	DIESEL	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH REAR-LIFT, SURROUND CAMERA SYSTEM, FORKLIFT BRACKET


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Radio/CD
- Manual sunroof
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Missing
Replace



2: Screen Front
Chipped
Over 10mm



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Chipped
Multiple Chips



8: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel osr
Hole
Over 10mm



10: Qtr Panel osr
Chipped
Multiple Chips



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Fascia Trim
Damaged
Replace



13: Dash Warning Lights
Displayed
No Action



14: Roof Lining
Holed
Over 3mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		No Excessive Smoking		OK	
Brakes		OK					
Parking Brake		OK					
EML light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		Fault	