

VEHICLE INSPECTION REPORT

PG66UFA

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Bedford

Reg. date 24/02/2017

Year 2017

Mileage 1,345,620 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G148327

Body Style Tractor Unit

Service history Yes

MOT Due 31/12/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

SURROUND CAMERA SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint




3: Bonnet
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Bumper Front
Scratched
UpTo 25mm Thru Paint

6: Door nsf
Dented
With Paint Damage



7: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm

8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	