

# VEHICLE INSPECTION REPORT

**YO190VC**

## Ford Transit Connect 240 1.5 ECOBLUE 100PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

### Details

Reg. date 13/05/2019

Year 2019

Mileage 123,129 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSKE73421

Body Style Panel Van L2

MOT Due 06/04/2026

CAP Clean £4,275.00

CAP Average £3,725.00

CAP Below £2,975.00

Gearbox MANUAL

Gears 6

\*WARNING LIGHT ON DASH\* AD BLUE, SINGLE SIDE DOOR

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Park assist camera
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Chipped  
Multiple Chips



2: Bonnet  
Chipped  
Multiple Chips



3: Screen Front  
Chipped  
UpTo 10mm



4: General Exterior  
Soiled  
Light



5: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



6: Wing nsf  
Chipped  
Multiple Chips



7: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



8: Door nsr  
Dented  
With Paint Damage





9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Lamp nsr  
Broken  
Replace




11: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm



12: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



13: Qtr Panel osr  
Dented  
Over 30mm



14: Seat Base Cover osf  
Holed  
Over 3mm



15: Carpets Front  
Holed  
Over 3mm

## Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK