

VEHICLE INSPECTION REPORT

NK20GZO

Land Rover Discovery 3.0 SD6 LANDMARK

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Buyer To Apply

Details

Location	Bedford	Colour	BLACK	CAP Below	£16,150.00
Reg. date	25/06/2020	VIN	SALRA2AK5L2424999	Gearbox	AUTOMATIC
Year	2020	Body Style	SUV	Gears	8
Mileage	66,295 Miles Not Warranted	MOT Due	03/12/2026	Doors	5
Fuel Type	DIESEL	CAP Clean	£18,900.00		
GVW	3200kg	CAP Average	£17,500.00		

WARNING LIGHTS ON DASH E/MIRRORS, KEYLESS IGNITION

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Front parking sensor
- Body coloured bumpers
- Alloy wheels
- Navigation system
- Air conditioning
- Park assist camera
- Front electric windows
- Rear parking sensor
- Rear electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Handle Outer nsf
Broken
Replace



5: Door nsr
Scratched
UpTo 25mm Thru Paint

6: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK