

VEHICLE INSPECTION REPORT

BT17ONH

Iveco Daily 70-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 19/05/2017

Year 2017

Mileage 110,994 Km Warranted

Fuel Type DIESEL

GVW 7000kg

Colour WHITE

VIN ZCFC270D305142941

Body Style Panel Van

Service history Yes

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Barn

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO2

NSI4

OSI4


NSO4





OSO3


Features

- Bluetooth connection
- Radio/CD
- Central locking
- Cruise control
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Panel Front
Cracked
Replace




3: Number Plate Front
Broken
Replace

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Over 30mm

8: Qtr Panel Moulding ns
Broken
Replace



9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



11: Bumper Rear Moulding
Broken
Replace

12: Door nsr
Chipped
Multiple Chips



13: Door osr
Dented
With Paint Damage

14: Qtr Panel osr
Dented
With Paint Damage



15: Wing osf
Dented
With Paint Damage

16: Door Pad osf
Broken
Replace



17: Fascia Trim
Damaged
Replace

18: Seat Base Cover osf
Holed
Over 3mm



19: Fascia Trim
Damaged
Replace

20: Seat Base Cover nsf
Soiled
Heavy



21: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		