

VEHICLE INSPECTION REPORT

KR68OSL

Mercedes-Benz Sprinter 3.5t H2 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£8,175.00
Reg. date	30/10/2018	Colour	WHITE	CAP Average	£6,925.00
Year	2018	VIN	WDB9076352P021483	CAP Below	£5,250.00
Mileage	114,364 Miles Not Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	08/03/2027	Gears	6

OUTSTANDING RECALL ON MOT - POSSIBLE INPUT ERROR ON MOT HISTORY AD-BLUE, SAT NAV, SIDE LOAD DOOR, TOW BAR

Tyres

NSF

NSR

OSF



OSR

Spare

Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Roof
Chipped
Multiple Chips



3: Wing nsf
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Chipped
Multiple Chips

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Chipped
Multiple Chips

8: Bumper Rear Moulding
Missing
Replace




9: Door nsr
Scratched
Over 25mm Thru Paint

10: Door nsr
Dented
Over 30mm




11: Door osr
Scratched
Over 25mm Thru Paint


12: Door osr
Dented
Over 30mm



13: Door osr
Scratched
Over 25mm Thru Paint

14: Qtr Panel osr
Scratched
Over 25mm Thru Paint





15: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

16: Door Mirror Assy osf
 Broken
 Replace



17: Screen Front
 Cracked
 Replace

18: Carpets Front
 Holed
 Over 3mm

Interior

Carpet Condition	Poor		Upholstery Condition	OK
Seat Condition	OK		Odour	No
Engine Runs	OK		No Excessive Smoking	OK
EML light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK			