

VEHICLE INSPECTION REPORT

PE17HUA

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 22/03/2017

Year 2017

Mileage 1,185,354 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G151674

Body Style Tractor Unit

Service history Yes

Service documents Printout

Last service date 09/12/2025

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3




OSO4


Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Dented
With Paint Damage

2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Thru Paint

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Panel Rear
Dented
With Paint Damage

8: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



9: Door osf
Dented
With Paint Damage

10: Door osf
Dented
With Paint Damage



11: Door Pad osf
Broken
Replace

12: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		