

VEHICLE INSPECTION REPORT

SG68XYJ

Fiat Ducato 42 2.3 Multijet II 180ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Location Doncaster

Reg. date 08/11/2018

Year 2018

Mileage 100,607 Miles
Warranted

Fuel Type DIESEL

GVW 5000kg

Colour WHITE

VIN ZFA25000002H64288

Body Style Minibus

Service history Yes

Service documents Printout

Last service date 22/06/2026

MOT Due 30/03/2027

Cab Type DAY CAB

Gearbox MANUAL

Rear Suspension Steel

161718 TACHO READING, 16 SEATS

Tyres

NSF

NSR

OSF


OSR

Spare


Features

- Bluetooth connection
- Air conditioning
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Cloth seat trim
- Digital radio

Photos



Condition Check



Damage Photos



1: Wing osf
Cracked
Replace

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Wing nsf
Cracked
Replace



5: Door Mirror Assy nsf
Broken
Replace

6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door Mirror Assy osf
Broken
Replace



9: Fascia Panel
 Broken
 Replace

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		OK	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			