

VEHICLE INSPECTION REPORT

SL62XEF

Volkswagen Crafter CR35 2.0 TDI 109PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Location Livingston

Reg. date 30/11/2012

Year 2012

Mileage 75,921 Miles
Warranted

Fuel Type DIESEL

GVW 3500kg

Colour WHITE

VIN WV1ZZZ2EZD6012436

Body Style Crew Van

Service history Full

Service documents Printout

MOT Due 23/10/2026

CAP Clean £2,550.00

CAP Average £2,000.00

CAP Below £1,325.00

Gearbox MANUAL

Gears 6

Axle Combi 4x2

TOW BAR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Seat Base Cover nsr
Torn
Over 3mm



2: Panel Front
Rusted
Over 5mm



3: Panel Rear
Rusted
Over 5mm

4: Door nsf
Dented
Over 30mm



5: Panel Rear
Rusted
Over 5mm

6: Panel Front
Rusted
Over 5mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK