

VEHICLE INSPECTION REPORT

BN21AHU

Iveco Daily 35-120

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	46443
Cap Code	IVDA23S352VDTM2 4 L

Details

Location	Bedford	GVW	3500kg	CAP Clean	£12,250.00
Reg. date	18/03/2021	Colour	WHITE	CAP Average	£11,000.00
Year	2021	VIN	ZCFC3358805387283	CAP Below	£9,000.00
Mileage	25,225 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	17/10/2026	Gears	6

SIDE DOOR IN-OP AD BLUE, SIDE LOADING DOOR, E/MIRRORS, AIR COMPRESSOR EQUIPMENT & 110V OUTLETS, 3520 WB

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Cracked
Replace

2: Wing osf
Chipped
1 To 5



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Dented
Between 10mm + 30mm



7: Door Moulding nsr
Broken
Replace

8: Door nsr
Dented
With Paint Damage




9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door osr
Dented
With Paint Damage

12: Qtr Panel osr
Dented
Between 10mm + 30mm



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK