

VEHICLE INSPECTION REPORT

AV70VPY

Fuso Canter 7C18

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Code	999900

Details

Location	Doncaster	GVW	7490kg	Gearbox	AUTOMATIC
Reg. date	30/11/2020	Colour	WHITE	Axle Combi	4x2
Year	2020	VIN	TYAFEB71ERDC02319	Rear Suspension	Steel
Mileage	214,476 Km Not Warranted	Body Style	Vacuum Tanker		
Fuel Type	DIESEL	Cab Type	DAY CAB		


WARNING LIGHTS ON DASH, VENDOR STATES GEAR BOX NEEDS FUSHING INSURANCE LOSS MAY OR MAY NOT APPEAR ON VCAR


Tyres					
NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Cruise control
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Door osf
Chipped
Multiple Chips



2: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Screen Front
Cracked
Replace



8: Fascia Panel
Broken
Replace



9: Seat Base Cover nsf
Soiled
Heavy



10: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault		
ABS light illuminated	OK		