

VEHICLE INSPECTION REPORT

GK19AWU

Man TGS 24.460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Gearbox	AUTOMATIC
Reg. date	10/05/2019	Colour	RED	Axle Combi	6x2
Year	2019	VIN	WMA24SZZ7KP126895	Steering Combi	Mid-Lift
Mileage	623,271 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	Cab Type	DAY CAB		

WARNING LIGHT ON DASH TWIN LINE PTO HYDRAULICS, SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL, LIGHT WEIGHT AXLE

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Navigation system
- Park assist camera


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Screen Front
Chipped
Over 10mm



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint




5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



7: Wing Front Arch Extension os
Broken
Replace



8: Door osf
Dented
Over 30mm





9: Door osf
Chipped
Edge Chip

10: Door Pad nsf
Missing
Replace



11: Door Pad osf
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Average		Average	
Average		-	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK