

VEHICLE INSPECTION REPORT

GL19FXB

Volvo FM 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Location	Bedford	GVW	44000kg	Gearbox	AUTOMATIC
Reg. date	10/04/2019	Colour	RED	Axle Combi	6x2
Year	2019	VIN	YV2XTY0C0KB895081	Steering Combi	Mid-Lift
Mileage	503,168 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	Cab Type	GLOBETROTTER CAB		

SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL, TWIN LINE PTO HYDRAULICS

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Cracked
UpTo 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint

4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint

6: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



7: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	