

VEHICLE INSPECTION REPORT

BKS003

Scania 111 Top Bunk (Unused) & Roof Lining Parts

Inspection		Vehicle		
		VAT	Margin	
		V5	N/A	
Details				
Location	Onsite Customer Auction	Mileage	Not Showing	VIN
Reg. date		Fuel Type		
Year		Colour		
Tyres				
NSF				
NSR				
OSF				
OSR				
Spare				

Photos



