

VEHICLE INSPECTION REPORT

HK17XXU

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Bedford

Reg. date 01/07/2017

Year 2017

Mileage 188,501 Km Not Warranted

Fuel Type DIESEL

GVW 16000kg

Colour ORANGE

VIN XLRAEL2700L465113

Body Style Dropside

MOT Due 30/06/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH

Tyres







NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Navigation system

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Bumper Front
Dented
With Paint Damage

6: Fog Lamp Surround ns
Broken
Replace



7: Wing Front Arch Extension ns
Broken
Replace

8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Seat Base Cover nsf
Holed
Over 3mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Hole
Over 10mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Bumper Rear
Rusted
Over 5mm

14: Wing Front Arch Extension os
Broken
Replace



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK