

VEHICLE INSPECTION REPORT

HN67NVG

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Bedford

Reg. date 17/11/2017

Year 2017

Mileage 240,665 Km Not Warranted

Fuel Type DIESEL

GVW 16000kg

Colour ORANGE

VIN XLRAEL2700L470341

Body Style Dropside

MOT Due 31/12/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

Tyres


NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos






Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Bonnet
Scratched
Over 25mm Thru Paint



5: Wing nsf
Scratched
UpTo 25mm Thru Paint

6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Wing Front Arch Extension ns
Broken
Replace

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




9: Door nsf
Scratched
Over 25mm Thru Paint

10: Bumper Rear
Rusted
Over 5mm



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint

12: Handle Outer osf
Broken
Replace



13: Door osf
Chipped
Edge Chip

14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

16: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK