

VEHICLE INSPECTION REPORT

FP70GJZ

Daf CF 430

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 12/02/2021

Year 2021

Mileage 343,292 Km Not Warranted

Fuel Type DIESEL

GVW 26000kg

Colour GREEN

VIN XLRASM4300G319047

Body Style Hookloader

Service history None

MOT Due 28/02/2027

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

HIAB BODY, MODEL ULT21S51-DCO-F (YEAR 2020), SHEETING SYSTEM, WEIGH SYSTYEM, DRAW BAR COUPLING


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Moulding
Missing
Replace

4: Bumper Front
Dented
With Paint Damage



5: Door nsf
Dented
With Paint Damage

6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Poor Previous Repair
Rippled UpTo 30%

8: Qtr Panel Moulding ns
Broken
Replace



9: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm

10: Door Mirror Assy osf
Broken
Replace



11: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		-
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				