

VEHICLE INSPECTION REPORT

LL18WRJ

Toyota Hilux 2.4 D-4D

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	38353
Cap Code	TOHL24ICN 7DTM4 6 L

Details

Location	Doncaster	Colour	WHITE	CAP Below	£5,325.00
Reg. date	14/06/2018	VIN	AHTHB3CD602126576	Gearbox	MANUAL
Year	2018	Body Style	Pickup Double Cab	Gears	6
Mileage	163,102 Miles Warranted	MOT Due	28/06/2027	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£8,225.00		
GVW	3210kg	CAP Average	£6,975.00		

E/MIRRORS

Tyres






NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Air conditioning
- Passenger airbag
- Cruise control
- Front electric windows
- Central locking
- Rear parking sensor
- Rear electric windows
- Cloth seat trim
- Digital radio
- Drivers airbag


Photos







Condition Check



Damage Photos




1: Wing osf
Chipped
Multiple Chips

2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm

6: Wing nsf
Chipped
Multiple Chips



7: C Post ns
Dented
With Paint Damage

8: Qtr Panel nsr
Dented
Over 30mm



9: Qtr Panel nsr
Rusted
Over 5mm

10: Tailgate
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage

12: Qtr Panel osr
Dented
With Paint Damage



13: Qtr Panel osr
Rusted
Over 5mm

14: Seat Base Cover osf
Torn
Over 3mm



15: Seat Base Cover nsr
Soiled
Heavy

16: Seat Base Cover nsf
Soiled
Heavy



17: In Car Entertainment
Broken
Replace

Interior

Carpet Condition		OK	Upholstery Condition		OK
Seat Condition		Poor	Odour		No
Engine Runs	OK		No Excessive Smoking		OK
EML light illuminated	OK		DPF light illuminated		OK
ABS light illuminated	OK				