

VEHICLE INSPECTION REPORT

LN67WMV

Ford Transit 350 2.0 TDCi 130ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 To Follow
Cap Id 37904
Cap Code FOTR20331R6DTM2 4
L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£3,700.00
Reg. date	30/09/2017	Colour	GREEN	CAP Average	£3,100.00
Year	2017	VIN	WF0XXXTTGXHB75150	CAP Below	£2,300.00
Mileage	118,951 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	08/05/2027	Gears	6

OUTSTANDING RECALL , AD-BLUE

Tyres

NSF

NSR

OSF

OSR






Spare

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Scratched
Over 25mm Thru Paint

4: Wing nsf
Scratched
Over 25mm Thru Paint




5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
Over 30mm

10: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

14: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



15: Bumper Rear Moulding
Broken
Replace

16: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Dented
Over 30mm

20: Qtr Panel osr
Scratched
Over 25mm Thru Paint



21: Qtr Panel osr
Scratched
Over 25mm Thru Paint

22: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



23: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

24: Screen Front
Chipped
Over 10mm



25: Seat Base Cover osf
Soiled
Heavy

26: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		