

VEHICLE INSPECTION REPORT

WV20HNX

Fiat Ducato 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44846
Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Bedford	GVW	3500kg	CAP Average	£6,150.00
Reg. date	29/06/2020	Colour	WHITE	CAP Below	£4,950.00
Year	2020	VIN	ZFA25000002N80143	Gearbox	MANUAL
Mileage	71,427 Miles Warranted	Body Style	Panel Van MWB	Gears	6
Fuel Type	Diesel	CAP Clean	£7,025.00		

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing and door
Chipped
1 To 5



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Broken
Replace




6: Qtr Panel Moulding ns
Missing
Replace



7: Door nsr
Dented
Over 30mm



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsr
Dented
Over 30mm



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Carpets Front
Holed
Over 3mm



14: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Average Average	Upholstery Condition		Average No
Seat Condition			Odour		
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK