

VEHICLE INSPECTION REPORT

WX20KNZ

Fiat Ducato 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44846
Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Bedford	GVW	3500kg	CAP Average	£6,500.00
Reg. date	29/06/2020	Colour	WHITE	CAP Below	£5,225.00
Year	2020	VIN	ZFA25000002N81976	Gearbox	MANUAL
Mileage	61,202 Miles Warranted	Body Style	Panel Van MWB	Gears	6
Fuel Type	Diesel	CAP Clean	£7,425.00		

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Screen Front
Chipped
Over 10mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel Trim ns
Missing
Replace



7: Qtr Panel nsr
Dented
Over 30mm



8: Door nsr
Dented
Over 30mm



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK