

VEHICLE INSPECTION REPORT

NX16VTN

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Bedford

Reg. date 01/03/2016

Year 2016

Mileage 694,295 Km Not Warranted

Fuel Type Diesel

GVW 18000kg

Colour WHITE

VIN WMAN18ZZ9GY340183

Body Style Curtainside

MOT Due 31/05/2027

Cab Type LX CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Rear Doors Barn

Tail Lift Tuckaway

TAIL LIFT IN-OP SURROUND CAMERA SYSTEM


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Park assist camera
- Air conditioning

Photos






Condition Check



Damage Photos



1: Wing of
Cracked
Replace



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Screen Front
Chipped
UpTo 10mm

4: Bumper Front
Cracked
Over 25mm



5: Bumper Front
Cracked
Over 25mm

6: A Post ns
Cracked
Replace



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Wing Front Arch Extension ns
Broken
Replace



9: Door nsf
Dented
With Paint Damage

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Over 30mm

12: Qtr Panel osr
Dented
Over 30mm



13: Qtr Panel osr
Hole
Over 10mm

14: Door osf
Chipped
Edge Chip



15: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm

16: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



17: Seat Base Cover osf
Torn
Over 3mm

18: Handle Inner osf
Damaged
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK