

VEHICLE INSPECTION REPORT

NX67RNZ

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Bedford

Reg. date 26/09/2017

Year 2017

Mileage 601,773 Km Not Warranted

Fuel Type Diesel

GVW 18000kg

Colour WHITE

VIN WMAN18ZZXGY340287

Body Style Curtainside

MOT Due 31/12/2026

Cab Type LX CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

Rear Doors Barn

Tail Lift Tuckaway

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: A Post os
Scratched
Over 25mm Not Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm




5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Qtr Panel nsr
Dented
Over 30mm



9: Door osf
Chipped
Edge Chip

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault